



DUNGOG WATER TREATMENT PLANT - OCTOBER MONTHLY POLLUTION MONITORING SUMMARY

Environment Protection Licence No. 3232

Date Obtained: 17 September 2012

Date Published: 3 October 2012

Licensee

Hunter Water Corporation
36 Honeysuckle Drive
NEWCASTLE WEST NSW 2302

QUALITY MONITORING

EPA Id. No. 1 Site Code 1610111		Site Description - Stormwater culvert at boundary of plant on the north side of Wade Street									
Pollutant	Unit of Measurement	Sampling Frequency	Monthly Summary #REF!								
			Minimum	Mean Value	Median Value	Maximum	3DGM Limit	3DGM Actual	100%ile Limit	100%ile Actual	Within Limits
Total Suspended Solids	milligrams per litre	Monthly	1	1	1	1	N/A	N/A	50	1	Yes
Aluminium	milligrams per litre	Monthly	0.17	0.17	0.17	0.17	N/A	N/A	N/A	N/A	N/A
Iron	milligrams per litre	Monthly	1.98	1.98	1.98	1.98	N/A	N/A	N/A	N/A	N/A
Manganese	milligrams per litre	Monthly	0.80	0.80	0.80	0.80	N/A	N/A	N/A	N/A	N/A
pH	pH	Monthly	6.99	6.99	6.99	6.99	N/A	N/A	N/A	N/A	N/A