HUNTER WATER SECTION s170 REGISTER



ITEM NAME:

North Lambton High Level Tank

	Item detailsDescription	 Historical Overview Management 	Heritage Status	 Heritage Significance References 	
ITEM DETA	ILS				
ltem Name Other / Former	<u> </u>	h Lambton High Level Tank nit Street High Level Tank			
NSW SHI No. 363002		024			
GID Plant No.	4207 WR-1	26 NOL-002-HLT			
Local Government AreaNewcastleLot and DPLot 90–91 DP 22741Address10 Summit Street, North Lambton NSW 2299					
Curtilage The curtilage of this asset is defined by its legal allotment boundaries (defined by the relevant Lot					ant Lot and



DP).

View of the North Lambton High Level Tank



Asset location and curtilage (red boundary) (refer to Figure 1 for additional detail)



HISTORICAL OVERVIEW

Current Use	Decommissioned
Former Use	Water storage
Designer / Builder	Hunter District Water Board
Historical Notes	With the threat of water shortages in the elevated areas around Newcastle in the early 1950s, the Hunter District Water Board purchased a number of high-level tanks to distribute throughout the high-risk areas. The North Lambton High Level Tank was completed in 1953.

HERITAGE STATUS Listing Details S170 Heritage and Conservation Register Local heritage listing State heritage listing **Conservation Management** N/A \square Plan Heritage Asset Action Plan N/A \square AHIMS search undertaken on 4 November 2022. No sites were registered in or within 50 metres Aboriginal Sites Registered of the relevant Lot and DP. within the Site Not assessed. Historical Archaeological Potential

н	ERIT	AG	E SI	GNI	FIC	AN	CE

Level of Significance	Local			
Statement of Significance	The North Lambton High Level Tank is a typical, well-designed example of a small-scale of steel tank designed to address local water pressure issues. It is one of only a few represse examples of this type of infrastructure remaining in the Hunter Water network and the olisted on the s170 Register.			
NSW SHR Criteria	 Aistorical Associative Aesthetic / Technical Aostal Social Research Potential (yield new information) f) Rare Representative 			
Significant Elements	• Overall form, shape, and scale of the tank.			

	C		\bigcirc	i		6	
--	---	--	------------	---	--	---	--

(

盫

9

DESCRIPTION	
Setting	Located on a vacant block in a residential area. A modern brick building sits at the rear of the allotment.
External Appearance	The structure comprises a segmented steel tank supported on five legs. An access ladder is attached to the southern aspect of the structure. Barbed wire is wrapped around the lower portion for security. The entire structure has been painted khaki.
Internal Appearance	N/A
Overall Condition	Fair.
Moveable Heritage Objects	None identified.

MANAGEMENT

Approval and Assessment Requirements	Minor or inconsequential impacts: Anything other than routine repair and maintenance must be discussed with the Environment Team to determine the level of heritage assessment required.				
	More than minor or inconsequential impacts: As above. Additionally, consultation with the relevant local council is required.				
	Demolition or removal from the register requires consultation with Heritage NSW and archival recording.				
General / Ongoing Management	• Changes within the defined curtilage should be preceded by the appropriate level of heritage assessment and approval. Advice and/or confirmation should be sought from the Environment Team prior to undertaking any works.				
	Maintain overall form, shape and scale of the structure.				
	 The introduction of new buildings or structures within the curtilage is discouraged. If introduced, the ability to view the structure 'in the round' is to be retained and not obscured. 				
Priority Conservation Works	 Monitor and manage peeling lead paint and corrosion of underlying metal where left exposed. 				

KEY IMAGES



Image 1: The High Level Tank



Image 2: Supporting beams beneath the storage tank



(Ø)





Image 3: Base of the High Level Tank

Image 4: Access ladder

REFERENCES

- Clem Lloyd, Patrick Troy and Shelley Schreiner 1992, For the Public Health. The Hunter District Water Board 18921992. • Publisher: Longman Cheshire Pty Ltd, Melbourne.
- Department of Public Works, Annual Reports, 1888 to 1892 and 1893-94 to 1960-61.
- Futurepast Heritage Consulting Pty Ltd, 2010, 'Hunter Water Conservation and Heritage Register Study'.
- Glennie Jones 1967, The Movement for Newcastle's First Water Supply 1875-1885, Newcastle History Monographs No. 2. . Publisher: The Council of the City of Newcastle, Newcastle.
- Hunter District Water Board, Annual Reports, 1938-39 to 1987-88. •
- Hunter District Water Supply and Sewerage Board, Annual Reports, 1897-98 to 1937-38.
- Hunter Water Board, Annual Reports, 1988-89 to 1990-91.
- Hunter Water Corporation, Annual Reports, 1991-92 to 2008-09.
- John W Armstrong 1967, Pipelines and People. The History of the Hunter District Water Board Newcastle, New South Wales. Publisher: The Hunter District Water Board, Newcastle.
- Mal Hindley 1983, 'From Weirs, Dams and Sand', in Shaping the Hunter. Publisher: The Newcastle Division of the Institute of Engineers Australia, Newcastle.



In partnership with



